Longo Estonia OÜ is part of the international company Longo Group, which is active in the field of used car trade. The company sets high standards offering a fully transparent and reliable purchase, sale and financing for used cars. The company values transparency, honesty and professional approach in everyday processes. The whole process, starting with the purchase of a car in the Netherlands, up to its export to Estonia, technical inspection and registration in Estonia, is done inside the company and the team of professionals takes care of it. Because of this, we are proud to offer a **lifetime guarantee for vehicle history.**

longo Certified

With respect to RENAULT CAPTUR with VIN number VF12RDA1H52327070
Longo Estonia OÜ certifies that:

✓ Netherlands is this car's first and only registration country

- *This car for the first time on 04.2015 has been registered in the Netherlands and is the first and only country of registration for this car. It has never been registered in any other country. Vehicle was exported to Estonia on **.**.** and received its registration on **.**.**.*

✓ This car has a complete and verified ownership history

- *This car has always been used as a personal vehicle. It has not been used as a taxi or rental vehicle, in a commercial setting or as a service or government car.*

✓ This car is not encumbered by any financial commitment or obligation.

- *The car was exported from the Netherlands by Longo Group JCS and all procedures have been followed with all taxes and fees paid. It is not subject to any commitments or obligations towards a third party.*

✓ The mileage of this car is original and has not been modified.

- *The history of this car's mileage is true and tested in the Dutch National Vehicle Register. Thanks to a system that has been in operation for over 25 years, for every car, that is registered in Netherlands could be requested Tellerrapport (RDW) report - that provides full information about its owner as well as the odometer. Thanks to this, the customer can be sure that car's with VIN no. VF12RDA1H52327070 odometer is true and has not been modified when imported in Estonia.*

✓ This car is in good technical condition

- *We have checked this car and confirm that it has never been involved in major accidents, has regular maintenance, as well as mandatory roadworthiness tests in the country of export. In Estonia, this car has passed obligatory technical inspection too.*

Jacob Hoogenboom
Longo Group, COO

15.11.2026

Buy respectfully, drive joyfully!

EXAMPLE

Lifetime guarantee for vehicle history.

Buying process for a used car must be as safe, transparent, fair and easy as buying a new car. Therefore, Longo Estonia OÜ imports cars with verified origin, ownership and mileage history and which have not been involved in major accidents. For your convenience and reassurance, please see below summary of important parameters for selected car.

longo Certified

Basic

Make, model	RENAULT CAPTUR Helly Hansen
VIN number	VF12RDA1H52327070
First registration in Estonia	**.**.**
Number plate no.	OR1214
Mileage	168 460
Fuel type	Petrol
Obligatory technical inspection valid till	08.04.27

Vehicle history

First registration date	04.2015
Country of origin	Netherlands
Last owner	Longo Netherlands BV
Ownership history	available
Mileage history	available/logic
Detailed Technical inspection history	available
Encumbrances	not registered
Import date in Estonia	**.**.**

EXAMPLE

Longo Estonia OÜ is part of the international company Longo Group, which is active in the field of used car trade in Eastern Europe. The company sets high standards offering a fully transparent and reliable purchase, sale and financing for used cars. The company values transparency, honesty and professional approach in everyday processes. Our vision is to become the most recognizable and reliable car sales company in the used car trade.

Buy respectfully, drive joyfully!