

Diagnosis report of 2018 PEUGEOT 308 GT-line



Car details

Color: Grey	CO ₂ NEDC Emission: 120 g/km
Fuel type: Petrol	CO ₂ WLTP Emission: 141 g/km
Body type: Hatchback	Gross Vehicle Weight (GVW): 1750 kg
Number of doors: 5	Engine size: 1.20 l
Number of seats: 5	Cylinders: 3
Mileage: 160 281 km	Power: 96 kw
VIN Code: VF3LPHNSPJS133312	Fuel consumption: 5.20 l/100km
Gearbox: Manual	Tire size: 225/45 - 17"
Drive type: Front-Wheel Drive	Longo Stock ID: N062533
Longo Certified	

Car photos



Disclaimer

This report has been generated automatically using the information available in our systems and may not be fully comprehensive or complete. Automated translation technology was used in its preparation, and as a result, minor inaccuracies may occur. If you have any questions or if any part of the report is unclear, please do not hesitate to contact our sales team. They will be happy to assist you.

Diagnosis report of 2018 PEUGEOT 308 GT-line



Diagnosis details

Mileage on completion date: 160 281 km

Checked by Longo Shared Service certified diagnostics team: Eimantas A., Arnas S.

This vehicle has been inspected in accordance with the Longo 150-point checklist, covering the body exterior, interior, and mechanical condition. Based on the inspection performed and the information available at the time of assessment, no indications of involvement in major accidents were identified. Information regarding maintenance history and mandatory roadworthiness inspections is based on available documentation and records from the country of export. Please note that certain general wear and tear issues are considered acceptable and may not be repaired.

Summary of diagnosed issues


During the comprehensive diagnosis conducted by Longo, 10 issues were identified in the vehicle.

Interior	Exterior	Mechanical
✔ 1 issues identified	✔ 1 issues identified	✔ 8 issues identified

Diagnosis process



OBD II diagnosis




Interior

✓ 1. Inside: Trims - Condition



Exterior

✓ 1. Side: Wheels - Condition



Mechanical

✓ 1. OTHER: Front Brake Discs Including Pads



✓ 2. OTHER:

✓ 3. OTHER:

✓ 4. OTHER: Rear Brake Discs With Pads



✓ 5. OTHER:



✓ 6. OTHER: Oil Pan



✓ 7. OTHER: Suspension Lower Arm



✓ 8. OTHER:

Other

1. Diagnostic Photo



2. Brake Test Line Results



3. Air-Conditioning Measurement



✓ 4. Add Photo of Front Interior



Preparation and repair report of 2018 PEUGEOT 308 GT-line



Summary of work performed in Longo Preparation center

During the preparation process, the following works were performed

Mechanical repairs

- ✓ 1. Charge Battery
- ✓ 2. Oil Pan
- ✓ 3. Engine Oil and Filter
- ✓ 4. Camshaft Drive Belt

Cleaning & polishing

- ✓ 1. Body wet wash
- ✓ 2. Full interior deep clean using only hypoallergenic cleaning products

Spare parts used during preparation

- 1. Oil Filter (OP540/1)
- 2. Oil Pan Gasket (834.823)
- 3. Camshaft Drive Belt Kit (GATK05T360HOB)
- 4. 5W30 Quartz Ineo RCP 208L (5W30 QUARTZ INEO RCP 208L)

Disclaimer

This report has been generated automatically using the information available in our systems and may not be fully comprehensive or complete. Automated translation technology was used in its preparation, and as a result, minor inaccuracies may occur. If you have any questions or if any part of the report is unclear, please do not hesitate to contact our sales team. They will be happy to assist you.


Additional information about 2018 PEUGEOT 308 GT-line



Additional pictures













ONDERHOUDSHISTORIE			
Datum: 16.10.24 km-stand: 114.154,3 Normale Gebruiksomstandigheden ☐ Zware Gebruiksomstandigheden ☐		Datum: / / km-stand: / / Normale Gebruiksomstandigheden ☐ Zware Gebruiksomstandigheden ☐	
Periodieke onderhoudscontrole VAN MOSSEL PEUGEOT PEUGEOT DEALER Van Mossel Amsterdam Zuidpoort Glikkenbergweg 29, 1101 AK Amsterdam Zuidoost Tel: 088 - 0014500 www.vanmosselpeugeot.nl Stempel reparateur		Periodieke onderhoudscontrole Stempel reparateur	
Volgende controle bij 116.000 km of op 16.10.25		Volgende controle bij / / km of op / /	
Datum: / / km-stand: / / Normale Gebruiksomstandigheden ☐ Zware Gebruiksomstandigheden ☐		Datum: / / km-stand: / / Normale Gebruiksomstandigheden ☐ Zware Gebruiksomstandigheden ☐	
Periodieke onderhoudscontrole Stempel reparateur		Periodieke onderhoudscontrole Stempel reparateur	
Volgende controle bij / / km of op / /		Volgende controle bij / / km of op / /	

ONDERHOUDSHISTORIE			
Datum: 29. Dec. km-stand: 16365 Normale Gebruiksomstandigheden ☐ Zware Gebruiksomstandigheden ☐		Datum: 14.10.2021 km-stand: 81.065 Normale Gebruiksomstandigheden ☒ Zware Gebruiksomstandigheden ☐	
Periodieke onderhoudscontrole VAN MOSSEL PEUGEOT PEUGEOT DEALER Van Mossel Zuidoost Kleine Tacht 23, 1107 CB Zoosdorp Tel: 075 - 816 00 76 www.vanmossel.nl Stempel reparateur		Periodieke onderhoudscontrole Van Mossel Moorn De Marwijnse 59 1689 AR Zwaag T: +31 229 29 19 30 E: info@vanmosselpeugeot.nl Stempel reparateur	
Volgende controle bij 161.000 km of op Dec. 2021		Volgende controle bij 106.000 km of op 14.10.2022	
Datum: 30.10.22 km-stand: 105.720 Normale Gebruiksomstandigheden ☐ Zware Gebruiksomstandigheden ☐		Datum: 20.9.23 km-stand: 122.029 Normale Gebruiksomstandigheden ☐ Zware Gebruiksomstandigheden ☐	
Periodieke onderhoudscontrole VAN MOSSEL PEUGEOT PEUGEOT DEALER Van Mossel Amsterdam Zuidpoort Glikkenbergweg 29, 1101 AK Amsterdam Zuidoost Tel: 088 - 0014500 www.vanmosselpeugeot.nl Stempel reparateur		Periodieke onderhoudscontrole VAN MOSSEL PEUGEOT PEUGEOT DEALER Van Mossel Amsterdam Zuidpoort Glikkenbergweg 29, 1101 AK Amsterdam Zuidoost Tel: 088 - 0014500 www.vanmosselpeugeot.nl Stempel reparateur	
Volgende controle bij 125.000 km of op 20.10.23		Volgende controle bij 147.029 km of op 28.9.24	

ONDERHOUDSHISTORIE

De volgende bladzijden zijn bestemd voor het afdrukken door de reparateur die het onderhoud aan uw PEUGEOT uitvoert.

Wij raden u aan de facturen en documenten met betrekking tot het uitgevoerde onderhoud aan uw auto te bewaren.

De periodieke onderhoudscontroles zijn verplicht om te voldoen aan de garantievoorwaarden van de fabrikant.

Laat de reparateur van uw keuze hieronder de gegevens (datum, kilometerstand, volgende onderhoudscontrole) van uw auto invullen op basis van de gebruiksomstandigheden.

Wanneer u de auto doorverkoopt, dient u alle boordocumentatie over te dragen aan de nieuwe eigenaar.

DEET VLOOSSELE - 1
Inhoudsopgave

Datum: 30 Jan 2019	km-stand: 25998
Normale Gebruiksomstandigheden ☒	Zware Gebruiksomstandigheden ☐

Periodieke onderhoudscontrole

VAN MOSSEL PEUGEOT
PEUGEOT DEALER
Van Mossel Zoandam
Kleine Tocht 23, 1507 CB Zoandam
Tel. 075 - 616 00 74
www.vanmossel.nl/peugeot

Volgende controle bij 50.000 km of op 30 Jan 2020

Datum: 23 1 2020	km-stand: 51642
Normale Gebruiksomstandigheden ☒	Zware Gebruiksomstandigheden ☐

Periodieke onderhoudscontrole

VAN MOSSEL PEUGEOT
PEUGEOT DEALER
Van Mossel Zoandam
Kleine Tocht 23, 1507 CB Zoandam
Tel. 075 - 616 00 74
www.vanmossel.nl/peugeot

Volgende controle bij 76.200 km of op 23 1 2020

25





Longo 150-point checklist

Every vehicle is carefully examined according to Longo's comprehensive 150-point checklist, ensuring a thorough assessment mechanical condition. Depending on the factors such as condition, mileage, and specifications, additional checks may be included or omitted.



Vehicle Identity & History

Vehicle identification number (VIN) verified	Registration number confirmed	Mileage verified
Year of manufacture confirmed	First registration date confirmed	Service history checked
Last service date and mileage recorded	Next service due date recorded	Previous accident damage check performed
Manufacturer recall status checked	Vehicle documents verified	Number of keys checked

Exterior Condition

Front bumper inspected	Rear bumper inspected	Bonnet/hood inspected
Roof inspected	Left side panels inspected	Right side panels inspected
All doors inspected	Boot/trunk inspected	Fuel filler cover inspected
Tow bar (if fitted) inspected	Number plate condition confirmed	Paintwork overall checked
Rust or corrosion checked	Gaps between panels checked	Windscreen inspected
Rear window inspected	Side windows inspected	Sunroof/panoramic roof inspected

Interior Condition

Driver's seat condition checked	Passenger seats checked	Rear seats checked
Seat adjustment mechanisms tested	Seat heating/cooling tested (if fitted)	Seatbelts checked
Carpets inspected	Floor mats inspected	Headlining inspected
Interior trims inspected	Dashboard inspected	Door trims inspected
Armrest inspected	Parcel shelf inspected	Luggage area condition checked
Luggage area carpets checked	Luggage area lighting tested	Spare wheel / repair kit checked

Lights, Mirrors & Glass

Front headlights tested	High beam tested	Fog lights tested
Daytime running lights tested	Rear lights tested	Brake lights tested
Reverse lights tested	Indicators tested	Number plate lights tested
Side markers/reflex reflectors checked	Interior lights tested	Dashboard warning lights checked
Sun visors inspected	Interior mirror inspected	Exterior mirrors inspected
Electric mirror adjustment tested		

Comfort & Electronics

Air conditioning tested	Heating system tested	Ventilation system tested
Window heating tested (front/rear)	Power windows tested	Central locking tested
Remote key tested	Child lock tested	Infotainment screen tested
Radio tested	Navigation tested (if fitted)	Bluetooth connection tested
USB/12V sockets tested	Parking sensors tested	Rear view camera tested
Parking assistance systems tested	Cruise control tested	Steering wheel buttons tested
Horn tested	Electronic driver aids checked (lane assist, etc., if fitted)	

Safety Equipment

Airbags checked via system	Passenger airbag switch checked	ABS warning light checked
ESC/traction control checked	Tyre pressure monitoring system tested	Fire extinguisher/first aid kit present (if supplied)

Engine Bay & Fluids

Engine starts normally	Engine idles smoothly	Unusual engine noises checked
Engine mounts checked	Drive belts checked	Timing belt/chain condition checked
Battery condition tested	Battery charging tested	Alternator performance tested
Fluid leaks checked	Engine oil level checked	Engine oil quality checked
Coolant level checked	Coolant quality checked	Brake fluid level checked
Brake fluid quality tested	Power steering fluid level checked	Power steering fluid quality checked
Windscreen washer fluid filled	Fuel system checked for leaks	

Braking System

Front brake discs checked	Rear brake discs checked	Brake pads checked
Brake hoses checked	Brake lines checked	Parking brake tested
Brake pedal response tested	ABS function confirmed	

Steering & Suspension

Steering wheel alignment checked	Steering response tested	No excessive steering play confirmed
Power steering assistance tested	Front suspension inspected	Rear suspension inspected
Shock absorbers inspected	Springs inspected	Ball joints inspected
Wheel bearings checked		

Wheels & Tyres

Front tyres tread depth measured	Rear tyres tread depth measured	Tyre wear pattern checked
Tyre sidewalls inspected	Tyre pressures checked	Spare tyre condition checked
Alloy wheels checked for damage	Wheel nuts/bolts secure	Locking wheel nut present
Additional tyre set inspected (if included)		

Exhaust & Fuel System

Exhaust condition checked	Exhaust leaks checked	Catalytic converter present
Diesel particulate filter present (if fitted)	Fuel tank condition checked	Fuel lines inspected
Fuel filler cap tested		

Road Test & Driving Performance

Smooth acceleration confirmed	Smooth gear shifting confirmed	Clutch operation tested
Braking performance tested	Driving stability confirmed	