# Diagnosis report of
# 2020 PEUGEOT 3008 Executive Avantage

## Car details

| | |
|---|---|
| Color: White | $CO_2$ NEDC Emission: 114 g/km |
| Fuel type: Petrol | $CO_2$ WLTP Emission: 145 g/km |
| Body type: SUV | Gross Vehicle Weight (GVW): 1920 kg |
| Number of doors: 5 | Engine size: 1.20 l |
| Number of seats: 5 | Cylinders: 3 |
| Mileage: 163 982 km | Power: 96 kw |
| VIN Code: VF3MRHNSMLS233600 | Fuel consumption: 5.00 l/100km |
| Gearbox: Manual | Tire size: 215/65 - 17" |
| Drive type: Front-Wheel Drive | Longo Stock ID: N558937 |
| Longo Certified | |

## Car photos



**Disclaimer**

This report has been generated automatically using the information available in our systems and may not be fully comprehensive or complete. Automated translation technology was used in its preparation, and as a result, minor inaccuracies may occur. If you have any questions or if any part of the report is unclear, please do not hesitate to contact our sales team. They will be happy to assist you.

# Diagnosis report of
# 2020 PEUGEOT 3008 Executive Avantage

## Diagnosis details

**Mileage on completion date:** 163 982 km

**Checked by Longo Shared Service certified diagnostics team:** Arnas S., Mindaugas G.

This vehicle has been inspected in accordance with the Longo 150-point checklist, covering the body exterior, interior, and mechanical condition. Based on the inspection performed and the information available at the time of assessment, no indications of involvement in major accidents were identified. Information regarding maintenance history and mandatory roadworthiness inspections is based on available documentation and records from the country of export. Please note that certain general wear and tear issues are considered acceptable and may not be repaired.

## Summary of diagnosed issues

During the comprehensive diagnosis conducted by Longo, 3 issues were identified in the vehicle.



| Interior | Exterior | Mechanical |
|---|---|---|
| No issues found | No issues found | 3 issues identified |

## Diagnosis process






## OBD II diagnosis

## Mechanical

**1. OTHER:** Engine Oil & Filter Change

**2. BRAKES:** Front Brake Discs Both



**3. BRAKES:** Rear Brake Disc (Both)



## Other

### 1. Diagnostic Photo






### 2. Brake Test Line Results





### 3. Air-Conditioning Measurement



### 4. Add Photo of Front Interior



# Preparation and repair report of
# 2020 PEUGEOT 3008 Executive Avantage

## Summary of work performed in Longo Preparation center

During the preparation process, the following works were performed

### Mechanical repairs

- 1. Engine Oil & Filter Change

### Cleaning & polishing

- 1. Body wet wash
- 2. Full interior deep clean using only hypoallergenic cleaning products
- 3. Post cleaning body polish

### Spare parts used during preparation

1. Oil Filter (OP540/1)
2. Oil Pan Gasket (834.823)
3. 5W30 Quartz Ineo RCP 208L 3.5L

**Disclaimer**

This report has been generated automatically using the information available in our systems and may not be fully comprehensive or complete. Automated translation technology was used in its preparation, and as a result, minor inaccuracies may occur. If you have any questions or if any part of the report is unclear, please do not hesitate to contact our sales team. They will be happy to assist you.

Additional information about

# 2020 PEUGEOT 3008 Executive Avantage

## Additional pictures






MICHELIN



longo


longo








AUTOMOBILES PEUGEOT
e2*2007/46*0534
VF3MRHNSMLS233600
1920 KG
3320 KG
1 1150 KG
2 1050 KG
MRHNSM – C1P100


Radio OFF
km/h
163982 km
451.9 km



Radio OFF
km/h
163982 km
451.9 km


TotalEnergies
Oil: 5W30
Mileage: 163982
Date: 2026.10.13
Oil Filter Change:
Next Oil Change
Mileage: 173982
Date: 2024.10.13
Service Technician Signature:
Lengo
baltics.totalenergies.com






Leitzahl/
code number
N558937
PEUGEOT


ONDERHOUDSBEURTEN
Datum: 02 04 25
km-stand: 137568
Normale gebruiksomstandigheden
Zware gebruiksomstandigheden
De Autowerkplaats B.V.
Noord 80
2931 SL Krimpen aan de Lek
Volgende onderhoudsbeurt
bij 167568
km of op 02.04.26.
Datum: 7.5.2026
km-stand: 155706
Grote beurt
Distributieriem
JWA Autoservice
Jan van der Heijdenstraat 20
3281 LE Oud-Beijerland
0186 - 62 79 70
info@jwa-autoservice.nl
www.jwa-autoservice.nl
Periodiek onderhoud
Stempel professionele reparateur
* Welk van de twee als eerste wordt bereikt.


1
1/2
0
Service in 20000 km or
12 month(s)
163982 km





# Longo 150-point checklist

Every vehicle is carefully examined according to Longo's comprehensive 150-point checklist, ensuring a thorough assessment mechanical condition. Depending on the factors such as condition, mileage, and specifications, additional checks may be includ may be omitted.

| | | |
|---|---|---|
| **Vehicle Identity & History** | | |
| Vehicle identification number (VIN) verified | Registration number confirmed | Mileage verified |
| Year of manufacture confirmed | First registration date confirmed | Service history checked |
| Last service date and mileage recorded | Next service due date recorded | Previous accident damage check performed |
| Manufacturer recall status checked | Vehicle documents verified | Number of keys checked |
| **Exterior Condition** | | |
| Front bumper inspected | Rear bumper inspected | Bonnet/hood inspected |
| Roof inspected | Left side panels inspected | Right side panels inspected |
| All doors inspected | Boot/trunk inspected | Fuel filler cover inspected |
| Tow bar (if fitted) inspected | Number plate condition confirmed | Paintwork overall checked |
| Rust or corrosion checked | Gaps between panels checked | Windscreen inspected |
| Rear window inspected | Side windows inspected | Sunroof/panoramic roof inspected |
| **Interior Condition** | | |
| Driver's seat condition checked | Passenger seats checked | Rear seats checked |
| Seat adjustment mechanisms tested | Seat heating/cooling tested (if fitted) | Seatbelts checked |
| Carpets inspected | Floor mats inspected | Headlining inspected |
| Interior trims inspected | Dashboard inspected | Door trims inspected |
| Armrest inspected | Parcel shelf inspected | Luggage area condition checked |
| Luggage area carpets checked | Luggage area lighting tested | Spare wheel / repair kit checked |
| **Lights, Mirrors & Glass** | | |
| Front headlights tested | High beam tested | Fog lights tested |
| Daytime running lights tested | Rear lights tested | Brake lights tested |
| Reverse lights tested | Indicators tested | Number plate lights tested |
| Side markers/reflex reflectors checked | Interior lights tested | Dashboard warning lights checked |
| Sun visors inspected | Interior mirror inspected | Exterior mirrors inspected |
| Electric mirror adjustment tested | | |
| **Comfort & Electronics** | | |
| Air conditioning tested | Heating system tested | Ventilation system tested |
| Window heating tested (front/rear) | Power windows tested | Central locking tested |
| Remote key tested | Child lock tested | Infotainment screen tested |
| Radio tested | Navigation tested (if fitted) | Bluetooth connection tested |
| USB/12V sockets tested | Parking sensors tested | Rear view camera tested |
| Parking assistance systems tested | Cruise control tested | Steering wheel buttons tested |
| Horn tested | Electronic driver aids checked (lane assist, etc., if fitted) | |
| **Safety Equipment** | | |
| Airbags checked via system | Passenger airbag switch checked | ABS warning light checked |
| ESC/traction control checked | Tyre pressure monitoring system tested | Fire extinguisher/first aid kit present (if supplied) |
| **Engine Bay & Fluids** | | |
| Engine starts normally | Engine idles smoothly | Unusual engine noises checked |
| Engine mounts checked | Drive belts checked | Timing belt/chain condition checked |
| Battery condition tested | Battery charging tested | Alternator performance tested |
| Fluid leaks checked | Engine oil level checked | Engine oil quality checked |
| Coolant level checked | Coolant quality checked | Brake fluid level checked |
| Brake fluid quality tested | Power steering fluid level checked | Power steering fluid quality checked |
| Windscreen washer fluid filled | Fuel system checked for leaks | |
| **Braking System** | | |
| Front brake discs checked | Rear brake discs checked | Brake pads checked |
| Brake hoses checked | Brake lines checked | Parking brake tested |
| Brake pedal response tested | ABS function confirmed | |
| **Steering & Suspension** | | |
| Steering wheel alignment checked | Steering response tested | No excessive steering play confirmed |
| Power steering assistance tested | Front suspension inspected | Rear suspension inspected |
| Shock absorbers inspected | Springs inspected | Ball joints inspected |
| Wheel bearings checked | | |
| **Wheels & Tyres** | | |
| Front tyres tread depth measured | Rear tyres tread depth measured | Tyre wear pattern checked |
| Tyre sidewalls inspected | Tyre pressures checked | Spare tyre condition checked |
| Alloy wheels checked for damage | Wheel nuts/bolts secure | Locking wheel nut present |
| Additional tyre set inspected (if included) | | |
| **Exhaust & Fuel System** | | |
| Exhaust condition checked | Exhaust leaks checked | Catalytic converter present |
| Diesel particulate filter present (if fitted) | Fuel tank condition checked | Fuel lines inspected |
| Fuel filler cap tested | | |
| **Road Test & Driving Performance** | | |
| Smooth acceleration confirmed | Smooth gear shifting confirmed | Clutch operation tested |
| Braking performance tested | Driving stability confirmed | |