Diagnosis report of
2018 VOLVO V60 Momentum

Car details

Color: Blue	CO_2 NEDC Emission: 157 g/km
Fuel type: Petrol	CO_2 WLTP Emission: 173 g/km
Body type: Wagon	Gross Vehicle Weight (GVW): 2250 kg
Number of doors: 5	Engine size: 2.00 l
Number of seats: 5	Cylinders: 4
Mileage: 292 956 km	Power: 184 kw
VIN Code: YV1ZW25UDK1012990	Fuel consumption: 6.80 l/100km
Gearbox: Automatic	Tire size: 235/45 - 18"
Drive type: Front-Wheel Drive	Longo Stock ID: N229323
Longo Certified	

Car photos



Disclaimer

This report has been generated automatically using the information available in our systems and may not be fully comprehensive or complete. Automated translation technology was used in its preparation, and as a result, minor inaccuracies may occur. If you have any questions or if any part of the report is unclear, please do not hesitate to contact our sales team. They will be happy to assist you.

Diagnosis report of
2018 VOLVO V60 Momentum

Diagnosis details

Mileage on completion date: 292 956 km

Checked by Longo Shared Service certified diagnostics team: Arnas S., Mindaugas G.

This vehicle has been inspected in accordance with the Longo 150-point checklist, covering the body exterior, interior, and mechanical condition. Based on the inspection performed and the information available at the time of assessment, no indications of involvement in major accidents were identified. Information regarding maintenance history and mandatory roadworthiness inspections is based on available documentation and records from the country of export. Please note that certain general wear and tear issues are considered acceptable and may not be repaired.

Summary of diagnosed issues

During the comprehensive diagnosis conducted by Longo, 21 issues were identified in the vehicle.


Interior	Exterior	Mechanical
2 issues identified	11 issues identified	8 issues identified

Diagnosis process





OBD II diagnosis




Interior

1. Front: Steering Wheel - Condition



2. Doors: Door Rubber Seals





Exterior

1. Lights: Front Lights (City, Regular, Full Headlight, Fog, Indicator) - Basic Functioning, Damage, and Color







2. Lights: Rear Lights (Brake, Fog, Indicator) - Basic Functioning, Damage, and Color



3. Lights: Rear Lights (Brake, Fog, Indicator) - Basic Functioning, Damage, and Color



4. Front: Windscreen Integrity - Free from MOT-Excluding Damage




5. Front: Hood Opening and Holding Mechanism




6. Front: Front Bumper - Condition and Alignment



7. Front: Front Bumper - Condition and Alignment






8. Front: Hood - Visual Damage



9. Side: Body Panel Geometry






10. Rear: Rear Bumper - Condition and Alignment





11. Rear: Trunk - Visual Damage




Mechanical

1. OTHER: Engine Oil & Filter Change

2. OTHER: Change Tires





3. OTHER: Charge Battery

4. BRAKES: Front Brake Discs Both



5. BRAKES: Rear Brake Disc (Both)



6. BRAKES: Rear Brake Pads (All)



7. SUSPENSION: Ball Joint Lower



8. ENGINE: Camshaft drive belt cover



Other

1. Diagnostic Photo






2. Brake Test Line Results




3. Add Photo of Front Interior



4. Air-Conditioning Measurement



Preparation and repair report of
2018 VOLVO V60 Momentum

Summary of work performed in Longo Preparation center

During the preparation process, the following works were performed

Body & Interior

- 1. Windshield Repair
- 2. Right Rear Light
- 3. Change Rear Reflectors
- 4. Change Hood Opening Mechanism
- 5. Front Bumper Repair
- 6. Change Headlights
- 7. Correct Body Panel Geometry
- 8. Other: Fr bumper
- 9. Headlamp Alignment

Mechanical repairs

- 1. Change Tires
- 2. Engine Oil & Filter Change
- 3. Charge Battery

Paintshop

- 1. Paint Boot
- 2. Paint Rear Bumper

Cleaning & polishing

- 1. Body wet wash
- 2. Full interior deep clean using only hypoallergenic cleaning products
- 3. Post cleaning body polish

Spare parts used during preparation

1. Oil Filter (OE662/4)
2. Quartz Ineo Xtra EC6 0W20 208L 5.6L
3. Oil Pan Gasket (EL247804)
4. Michelin 235/45R18 Summer Tire (MICHELIN 235/45R18 SUMMER)
5. Reflector Right Hand (ZVV1469AR)
6. Hood release cable S60 32234713 (AUA184646)
7. Hood lock release cable V60 32234698 (FAU14032)
8. Headlight RH S60 32314191 (SGG1566)
9. Headlight lense RH S60 (BUD8455)

Disclaimer

This report has been generated automatically using the information available in our systems and may not be fully comprehensive or complete. Automated translation technology was used in its preparation, and as a result, minor inaccuracies may occur. If you have any questions or if any part of the report is unclear, please do not hesitate to contact our sales team. They will be happy to assist you.

Additional information about

2018 VOLVO V60 Momentum

Additional pictures






MICHELIN
235/45 R 18
OUTSIDE


longo


longo










FIRST AID KIT
VERBANDTASCHE

MADE IN SWEDEN
1140 kg
1160 kg
4050 kg
2250 kg
YV1ZW25UDK1012990
e4*2007/46*1315*02
VOLVO CAR CORPORATION
2018
19
723—16
MOMENTUM
VOLVO

18°C
09:02
0
km/h
P
R
N
D
READY
OFF


09:02
Set dest
Ahead
3D
500m
FM
M1 PLIUS
Connecting phone...
24°C
AUTO
24°C


TotalEnergies
Oil:
0W20
Next Oil Change
Service Technician Signature:
LONGO
baltics.totalenergies.com


QUICK GUIDE


09:02
M1 PLIUS
Connecting phone...
Car status
Service
Use Remote Diagnostics to enable a workshop technician to remotely read data from your car if you have encountered a problem. Contact your authorised Volvo retailer to use this service.
Messages
Status
TPMS
Service
To Service
337 days
29998 km
24°C
AUTO
24°C




LONGO

Longo 150-point checklist

Every vehicle is carefully examined according to Longo's comprehensive 150-point checklist, ensuring a thorough assessment mechanical condition. Depending on the factors such as condition, mileage, and specifications, additional checks may be includ may be omitted.

Vehicle Identity & History		
Vehicle identification number (VIN) verified	Registration number confirmed	Mileage verified
Year of manufacture confirmed	First registration date confirmed	Service history checked
Last service date and mileage recorded	Next service due date recorded	Previous accident damage check performed
Manufacturer recall status checked	Vehicle documents verified	Number of keys checked
Exterior Condition		
Front bumper inspected	Rear bumper inspected	Bonnet/hood inspected
Roof inspected	Left side panels inspected	Right side panels inspected
All doors inspected	Boot/trunk inspected	Fuel filler cover inspected
Tow bar (if fitted) inspected	Number plate condition confirmed	Paintwork overall checked
Rust or corrosion checked	Gaps between panels checked	Windscreen inspected
Rear window inspected	Side windows inspected	Sunroof/panoramic roof inspected
Interior Condition		
Driver's seat condition checked	Passenger seats checked	Rear seats checked
Seat adjustment mechanisms tested	Seat heating/cooling tested (if fitted)	Seatbelts checked
Carpets inspected	Floor mats inspected	Headlining inspected
Interior trims inspected	Dashboard inspected	Door trims inspected
Armrest inspected	Parcel shelf inspected	Luggage area condition checked
Luggage area carpets checked	Luggage area lighting tested	Spare wheel / repair kit checked
Lights, Mirrors & Glass		
Front headlights tested	High beam tested	Fog lights tested
Daytime running lights tested	Rear lights tested	Brake lights tested
Reverse lights tested	Indicators tested	Number plate lights tested
Side markers/reflex reflectors checked	Interior lights tested	Dashboard warning lights checked
Sun visors inspected	Interior mirror inspected	Exterior mirrors inspected
Electric mirror adjustment tested		
Comfort & Electronics		
Air conditioning tested	Heating system tested	Ventilation system tested
Window heating tested (front/rear)	Power windows tested	Central locking tested
Remote key tested	Child lock tested	Infotainment screen tested
Radio tested	Navigation tested (if fitted)	Bluetooth connection tested
USB/12V sockets tested	Parking sensors tested	Rear view camera tested
Parking assistance systems tested	Cruise control tested	Steering wheel buttons tested
Horn tested	Electronic driver aids checked (lane assist, etc., if fitted)	
Safety Equipment		
Airbags checked via system	Passenger airbag switch checked	ABS warning light checked
ESC/traction control checked	Tyre pressure monitoring system tested	Fire extinguisher/first aid kit present (if supplied)
Engine Bay & Fluids		
Engine starts normally	Engine idles smoothly	Unusual engine noises checked
Engine mounts checked	Drive belts checked	Timing belt/chain condition checked
Battery condition tested	Battery charging tested	Alternator performance tested
Fluid leaks checked	Engine oil level checked	Engine oil quality checked
Coolant level checked	Coolant quality checked	Brake fluid level checked
Brake fluid quality tested	Power steering fluid level checked	Power steering fluid quality checked
Windscreen washer fluid filled	Fuel system checked for leaks	
Braking System		
Front brake discs checked	Rear brake discs checked	Brake pads checked
Brake hoses checked	Brake lines checked	Parking brake tested
Brake pedal response tested	ABS function confirmed	
Steering & Suspension		
Steering wheel alignment checked	Steering response tested	No excessive steering play confirmed
Power steering assistance tested	Front suspension inspected	Rear suspension inspected
Shock absorbers inspected	Springs inspected	Ball joints inspected
Wheel bearings checked		
Wheels & Tyres		
Front tyres tread depth measured	Rear tyres tread depth measured	Tyre wear pattern checked
Tyre sidewalls inspected	Tyre pressures checked	Spare tyre condition checked
Alloy wheels checked for damage	Wheel nuts/bolts secure	Locking wheel nut present
Additional tyre set inspected (if included)		
Exhaust & Fuel System		
Exhaust condition checked	Exhaust leaks checked	Catalytic converter present
Diesel particulate filter present (if fitted)	Fuel tank condition checked	Fuel lines inspected
Fuel filler cap tested		
Road Test & Driving Performance		
Smooth acceleration confirmed	Smooth gear shifting confirmed	Clutch operation tested
Braking performance tested	Driving stability confirmed	